



PLUG



VIEW FROM
CABLE SIDE


RECEPTACLE



VIEW FROM
INSIDE CABINET

HIGH VOLTAGE 4 PIN CONECTOR
 PLUG : HA 3INSERT - LAPP 10.4310
 HOOD : HA 3 TOP ENTRY- LAPP 10.4265

RECEPTACLE: HA 4 INSERT- LAPP 10.4320
 HOOD : HA 4 SIDE ENTRY- LAPP 10.4235



CCW ROTATION

380-440 VAC


WIRING TO NE 60204-1 STD Y CONFIGURATION

MOTOR CIRCUIT

LOW VOLTAGE 6 PIN CONECTOR
 PLUG : STA 6 INSERT - LAPP 10.4881
 HOOD : HA 3 TOP ENTRY- LAPP 10.4265


RECEPTACLE: STA 6 INSERT- LAPP 10.4861
 HOOD : HA 4 SIDE ENTRY- LAPP 10.4235

PLUG




VIEW FROM
CABLE SIDE

RECEPTACLE



VIEW FROM
INSIDE CABINET



WARNING LIGHT CIRCUIT

ASSEMBLY NOTES:
 MALE PLUGS MOUNTED ON CABLE
 FEMALE RECEPTACLE SHIPPED LOOSE

DWG. TITLE 810-039 WIRING		HTI FILTRATION		810-039 WIRING SCHEMATIC				
PROJECT DESCRIPTION STANDUN CANFORMING SYSTEMS CE COMPLIANT FILTER		11820 WESTERN AVE. STANTON, CA 90680		A	09-06-02	SP	SP	AMEND PARTS LIST
DRAWING NO. 810-039 WD	REVISION A	CUST. CONTR. NO. -		REV.	DATE:	DRWN BY	CHKD BY	DESCRIPTION
CUSTOMER STANDUN CANFORMING SYSTEMS								